

2 - 96 Valiant Drive, Hull Type 3 Fire Risk Assessment



Prepared for:	Rebecca Franks, Building Safety Manager
Prepared by:	John Askew, Fire Risk Assessor, Holistic Fire Safety
Date:	17/10/2024
Document Reference:	HFS.HCC.ValiantDrive1.FRA.2.0



EXECUTIVE SUMMARY

- Significant findings identified in HFS.HCC.ValiantDrive1.FRA.2.0 & HFS.HCC.ValiantDrive1.AP.2.0: 10 actions
- Proposed next review date: 07/10/2025
- Assessment review type: T3
- Requirement for additional inspections prior to assessment review: It is advised that work streams are monitored by a competent person to ensure satisfactory performance/installation/levels of remediation.

	OV	ERALL BUILDING	RISK RATI	NG	
-	-	on measures observed a of ignition) at this buildin		this assessment, it is co	onsidered
LOW		MEDIUM	Х	HIGH	
-	nts observed	e building and the occup at the time of this asses Ild be:		-	
SLIGHT HARM		MODERATE HARM	Х	EXTREME HARM	
The overall risk rating f	or the buildin	g is considered to be:			
		MODERATE RISK			



Fire Risk Assessment - Version 2

07/10/2024 / John Askew / Valiant Drive Block 1

Complete

Site conducted	Valiant Drive Block 1, Hull City Council T4 FRA programme
Conducted on	07/10/2024 09:00 BST
Prepared by	John Askew

Location

Ross Cleveland House 2 - 96 Valiant Drive Hull HU9 4DX



Photo 1

Table of Contents

Inspection	3
1. General information	4
2. Floor plans and building plan	8
3. Construction	9
4. Occupancy	10
5. Evacuation strategy	11
6. Fire loss experience	13
7. Relevant fire safety legislation	14
8. Electrical sources of ignition	15
Communal Areas	15
Flats	16
9. Smoking	18
10. Arson, security & housekeeping	19
11. Heating system	21
12. Cooking arrangements	22
13. Lightning	23
14. Hazards introduced by outside contractors and building works	25
15. Hazardous substances	26
16. Cladding & wall coverings (spread of flames and fire)	27
Design and materials of external walls	27
Internal Surface Linings	28
17. Compartmentation & Fire Separation	30
Summary of findings from compartmentation survey	31
Conclusion	33
18. Means of escape from flats	35
19. Means of escape from common parts	37
20. Fire Doors	40
21. Means of warning	43
Detection and alarm systems within residential accommodation	44
Private & confidential	2/117

Evacuation alert system	45
22. Emergency escape lighting	46
23. Fire safety signs and notices	47
24. Extinguishing media and fixed systems	51
25. Other relevant fixed systems and equipement	52
26. Access and facilities for the fire service	53
Secure information box	54
Floor plan and building plans	55
Confirmation of Regulation 11 of the Fire Safety Regulations 2022	56
27. Resident and stakeholder engagement - communication & information	57
-	57
Fire doors	58
28. Management of fire safety	60
Media summary	63
-	116

Inspection

Responsible person (e.g. employer) or person having control of the premises:

Hull City Council

Address of premises:

Ross Cleveland House 2 - 96 Valiant Drive Hull HU9 4DX

Person consulted:

Mike White

Assessor:

John Askew

Report validated by:

William Davidson

Date of fire risk assessment:

07/10/2024

Date of previous fire risk assessment:

12/04/2023

Suggested date for review:

07/10/2025

1. General information

1.1. Dimensions/footprint:

252m2 per floor / Total 3024m2

1.2. In accordance with Regulation 3 Fire Safety (England) Regulations 2022, is the premises defined as a 'High-rise Residential' Building?

In accordance with Regulation 3 Fire Safety (England) Regulations 2022, Block 1 is defined as a 'High-rise Residential Building'.

1.3. Number of floors at ground level and above:

Ground floor and x 11 upper floor levels.

1.4. Number of floors entirely below ground level:

None.

1.5. Floors on which car parking is provided:

None. External parking is provided for residents and visitors.

1.6 Age:

The building is believed to be constructed in the 1960's, however the block underwent renovation in the late 1990's.

1.7. Number of flats:

There are x48 residential dwellings in total, with x4 residential dwellings on all floors.

Block 1 is a general needs premises.

1.8. General description external:

Since the point of construction, the premises has undergone several cycles of refurbishment, one of which included the installation of a partial cladding / external wall system.

Following the Grenfell Tower tragedy, HCC commissioned UK LPP to complete a series of surveys on external cladding and external wall systems to HRBB's across Hull in 2017. Although findings of surveys confirmed that external walls systems met the functional requirements of Building Regulations and did not contain ACM's, reports provided limited information and potentially fall short of today's benchmarks for a PAS 9980 external wall survey.

Taking into consideration developments within the sector surrounding external wall systems, Holistic Fire Safety feel it would be prudent to undertake further surveys to confirm provisions. Surveys will provide assurances to the Building Safety team that external wall systems are compliant without exposing occupants to unnecessary risk.



Photo 2

1.9. General description of basement:

N/A.

1.10. General description ground floor:

The ground floor is made up of four residential flats, two service risers, a cleaners cupboard, pump room and two passenger lifts; one of which serves even floor numbers and the other odd floor numbers.

All flats, service risers and ancillary accommodation discharge into the lift lobby; however they are all separated from the single stairway by notional fire resisting doorsets.

The escape stair provides access to open air via two single final exits doors, both of which open in the direction of travel.

Accessed externally on the ground floor is the refuse collection point (bin store) and the boiler room for Valiant Drive Blocks 1, 2 & 3.

22291-VLTD1-01Aprov1-22291-VLTD1-00.pdf

1.11. General description of flats:

Residential flats are single and two bed occupancies whereby all habitable rooms discharge onto the internal hallway. Means of escape within flats are typical of diagram 3.3 of ADB B1 which does not require flats to have a protected internal hallway. This principle was based on limiting travel distances to circa 9m which in turn reduces the chance that residents could become trapped in the event of a fire. Additionally, cooking facilities are remote from the entrance door and do not prejudice the escape route from any point in the flat.

1.12. General description of means of escape:

Attached: First Floor Plan.

Means of escape are of simple design and construction whereby all flats are separated from the common escape stairway by two sets of self closing notional fire resisting doors which create a lobbied approach adjacent to the stair.

Once access is made into the common escape stair, ultimate safety is achieved by two single final exit doors which open in the direction of travel and are operated by two single action mechanisms.

Means of escape are consistent on all upper floors as lobbies are ventilated by manually opening windows and louvred vents; however the common escape stair is not provided with ventilation at the head.

All doors which form part of the escape routes are self-closing, notional FD30s fire doorsets.

22291-VLTD1-01Aprov1-22291-VLTD1-01.pdf

1.13. General description of service risers:

Service risers are consistent throughout the entire height of the building in terms of size, volume & type of services present; and all display defects in compartmentation.

Each riser is a shared enclosure as all services within them serve neighbouring flats.

Risers are continuous and extend the full height of the building. Risers contain electrical service cables, soil pipes, non-combustible pipework and combustible pipework. Risers are generally a sterile environment, however, as displayed in all other high-rise blocks, there are several breaches which are to be addressed and are highlighted in the compartmentation survey.

Risers are partially separated from escape routes by fire resisting construction providing 60 minutes, although fire resisting doorsets and fanlights are displaying evidence of significant deterioration/inappropriate construction and ventilation grilles which allow the passage of smoke to enter means of escape in the event of an incident.

It has been confirmed doors are to be replaced, although no date has been set as they are to be part of a larger programme of works which requires approval from the Building Safety Regulator.



Photo 3



Photo 4



Photo 5

1.14. General description of ventilation risers:

None.


There are no risers as such, however the block is provided with what is believed to be shunt ducts to provide extract from bathrooms (this does not apply to kitchens). It is suspected that ducts travel the full height of the building, serving a large number of flats vertically before terminating at roof level.

A piece of paper was held up towards the vent and there was no evidence of draw meaning that effluent / smoke would likely pool rather than enter the duct.

It has been traditional for many years for the common extract from bathrooms to incorporate shunt ducts, which reduce the likelihood of fire and smoke-spread between flats.

Fire dampers are provided in ductwork at the point extraction exits bathrooms in residential dwellings and enters central shafts. Bathrooms sampled (Flat 12) gave evidence of x2 vents (high/low level) which have dampers installed which are activated via a fusible link.

Although dampers do not restrict the spread of smoke in the early stages of a fire, it would prevent spread of flames and hot gases.



1.15. General description of chute system:

There is a single refuse chute provided at Block 1, however there are disposal points on each floor, located in permanently ventilated areas and separated from the common escape stair by fire resisting construction providing 30 minutes.

The refuse chute has undergone refurbishment and provides adequate protection at all floor levels with self-closing, intumescent lined hopper disposal points and an automatic isolation shutter which is activated by means of a fusible link at the base of the chute. The base of the chute is accessed externally.



Photo 7



Photo 8



Photo 9



Photo 10

2. Floor plans and building plan

In relation to Regulation 6 of the Fire Safety Regulations 2022, the responsible person in relation to a high-rise residential building must prepare a plan for each floor of the high-rise residential building. The floor plans must, together, identify the location of all lifts and identify if the lift is one for use by firefighters or an evacuation lift, and the key fire-fighting equipment in the whole building. Plans must include the following:

• Surrounding area of building detailing points of access, emergency response routes/appliance positioning

- Building dimensions
- Confirmation of number of storeys basement/parking, ancillary, residential floors, roof
- Location of different accommodation types in building single bed/two bed/maisonette
- Inlets for dry riser/wet riser
- · Isolation valves for active systems
- Firefighting access points firefighting shaft
- Location of secure information box
- Location of smoke control systems
- Key points of building stairway, risers, lobbies (smoke containment locations)
- Evacuation alert system location

2.1. Has the responsible person prepared a plan for each floor of the high-rise residential building and do plans meet the requirements of Regulation 6 of the Fire Safety Regulations 2022?

Holistic Fire Safety have prepared a plan for each floor at Block 1. Floor plans identify points of access, means of escape, as well as assisting to identify the location of all lifts and key fire-fighting equipment.

22291-VLTD1-01Aprov1-22291-VLTD1-00.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-01.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-02.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-03.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-04.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-05.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-06.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-07.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-08.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-09.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-10.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-10.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-09.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-01.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-01.pdf

3. Construction

3.1. Describe the standard and methods of construction which make up the premises:

Due to its construction being circa 1960's, it is likely that Block 1 was constructed to British Standard Code of Practice `CP3 Chapter IV, Precautions against fire – Fire precautions in flats of 80 feet or above`.

Bryant Bison 340: The industrialised building system consisted of load-bearing precast concrete wall and floor units, jointed on site with in-situ concrete and dry packed mortar after erection. In tower blocks over 12 storeys in height, all of the walls were load-bearing - external and internal.

Wimpey-No Fines: Constructed from cast in-situ concrete, No-Fines was one of the most successful system built houses. The wall construction contains no sand fraction using 1/2" to 3/4" stone aggregate mixed with cement. This creates a honeycomb type structure within the concrete. The construction of the system is similar to that of traditional solid walled masonry properties and offers a high level of robustness.

Whether or not the building was constructed to 'CP3 Chapter IV', Block 1 focuses upon the principle of compartmentation of both the staircore, ancillary accommodation and flats.

Due to reduced travel distances within flats, they are not required to have an internal 'protected' hallway to create a place of relative safety before the flat can be evacuated.

Subsequently, this supports a 'stay put' strategy based on the level of compartmentation together with additional features, including the external fabric. As a result, it was predicted that the block would withhold and minimise any fire situation to a relatively small area.

4. Occupancy

4.1. In relation to Approved Document B Volume 1. 2019, the purpose group is:

1(a) Flats

4.2. In relation to BS 9991:2015 (BS 9999:2017) Fire safety in the design, management and use of (residential) buildings, the risk profile is:

The risk profile for General Needs occupants is considered to be:

'Ci' (long term managed occupancy of mainstream housing of general needs with no special features with `low/medium` fire growth of 0. 012 kJ/s³ by evenly distributed low to mid level fire loading compromising a mix of combustible materials).

4.3. Estimated total occupancy on a normal day to day basis:

Circa 100

4.4. Max number of employees:

<5.

There are no permanent staff working within the building, however the block is provided with a caretaker. HCC operate a caretaker scheme whereby a representative of HCC ensures the day to day running of the block by carrying out tasks such as reporting antisocial behaviour, maintaining housekeeping and liaising with residents to resolve issues.

In addition, housing officers regularly attend site for specific duties such as routine testing and maintenance. Lone working is avoided where possible, however due to the nature of some activities, lone working is inevitable for low risk tasks; therefore staff operate and adhere to the corporate lone working policy.

4.5. Max number of residents and visitors at any one time:

Circa 120

4.6. Vulnerable groups - contractors, lone workers, care workers:

It was confirmed by HCC representatives that some residents occupying the block are defined as vulnerable and that anti-social behaviour occurs on a regular basis. It was also confirmed that substance misuse is a common occurrence which increases the likelihood of fire should residents be under the influence of alcohol or drugs.

It is possible residents will receive treatment from care and social workers on a periodic basis. All care provided is independent to HCC. Numbers should not exceed 5 at any one time, however it is likely that people providing care are unfamiliar with the premises.

All contractors adhere to a strict 'control of contractors' policy which includes a selection process, the receipt of RAMS & Insurance, site induction and a permit system where necessary. It is advised that an induction is carried out by all contractors used by HCC. A generic safety pack should be provided to contractors which ensures they are familiar with emergency procedures and actions to be taken in the event of fire. Contractors should read and sign the document; this will ensure HCC are controlling contractors appropriately and meeting the requirements of Article 5(4a).

Fire action notices are displayed prominently to instruct those who are unfamiliar with the building of actions to be taken in the event of an incident.

5. Evacuation strategy

5.1. The evacuation strategy for the building is:

As detailed within the 'Fire safety in Flats' booklet provided by HCC to residents; flats are designed to delay the spread of fire, therefore occupants should be 'relatively' safe to remain within their flats. HCC currently advise residents to:

- Evacuate the building in the event of a fire in a resident's flat
- Evacuate the building if a resident is aware of a fire in a nearby flat

The simultaneous evacuation of multiple flats/floors could potentially hinder the responding Fire & Rescue Service operational crews as evacuating residents could compromise the means of escape delaying firefighting operations; it is therefore essential that levels of compartmentation meet the necessary requirements to support a 'stay safe, stay put' strategy.

5.2. Have Person Centred Fire Risk Assessments (PCFRA's) been completed on all vulnerable residents?

Sue Houlton & the Housing team have completed a significant exercise to establish those residing within the building who required assistance with evacuation. Where necessary, person centred fire risk assessments (PCFRA) and personal emergency evacuation plans are to be created.

None confirmed at Block 1.

5.3. Are Personal Emergency Evacuation Plans (PEEPS's) in place for vulnerable residents?

PEEPs are in place for a number of residents at Block 1 with information held in the Secure Information Box; Should any resident's complete an 'Emergency Evacuation Support Request Form', this will trigger a PCFRA and subsequent PEEP.

5.4. Are PEEP's readily available to responding Emergency Services in the Secure Information Box?

Discussions have been held with Humberside Fire & Rescue Service (HFRS) and HCC to confirm how they prefer to receive information. Although traditionally PEEP's are stored on site within the Secure Information Box, it has been highlighted that HFRS may in fact prefer to receive information electronically so that it can be accessed via the appliance mobile data terminal. It has been confirmed HFRS do not require this information to be provided electronically.

5.5. Is the building is provided with an 'Assembly Point' / 'Muster Point'. Where applicable, is its location suitable is design and location?

The fire assembly point is located on the grassed area to the front of the blocks.



Photo 11

The assembly point should be located far enough away from the building to afford protection from heat and smoke in a fire situation but not so far away as to discourage people from using it.

Fire assembly points should be in positions that do not put staff, visitors and users of the building at risk from emergency vehicles responding to the incident, or from general/other traffic in the vicinity. Therefore, the assembly point should be located away from and off the vehicle access routes leading to the building. Ideally the assembly points should be located so as not to require the crossing of a road or movement through trafficked areas. The assembly points should be a temporary gathering area where it can be immediately determined if everyone is out of the building. Appropriate decisions should be made with regard to continuance of use for longer durations. This is particularly useful in the event of a 'partial' or 'full evacuation' of the residential areas by the Fire Service using the evacuation and alert system

6. Fire loss experience

6.1. Has there been any incidents involving fire which has resulted in loss/ damage/affected resident safety?

Following discussions with HCC representatives, there has been no incidents in the last 12 months.

7. Relevant fire safety legislation

Regulatory Reform (Fire Safety) Order 2005 The Fire Safety Act 2021 The Fire Safety (England) Regulations 2022 Health and Safety at Work etc Act 1974 (Sections 2,3 & 4) Housing Act 2004 & Housing and Planning Act 2016

References and supporting guidance is detailed at the end of the report.

7.1. The above legislation is enforced by:

The Local Authority Fire & Rescue Service - Humberside Fire and Rescue Service (HFRS).

7.2. Are there any notices in force applicable to the building - Alterations / Enforcement / Prohibition?

None.

8. Electrical sources of ignition

Communal Areas

8.1. Are fixed installations periodically inspected and tested?

Electrical testing and maintenance of the hard wiring of the building has been completed by Kingstown Works Limited (KWL), it was confirmed that all EICR reports for the building are held electronically by nominated HCC representatives.

It was also confirmed that there is an EICR programme in place and a legal action procedure implemented for any customers who are not providing access. Samples taken within communal areas (expiry 04/2029) gave satisfactory test frequencies.

8.2. Are Electrical Installation Condition Report (EICR) labels displayed to indicate the date of the most recent periodic inspection and the date of the next 5-year periodic inspection?



Photo 12

8.3. Have all 'C' deficiencies been are completed within allocated timeframes?

It was confirmed that all 'C' deficiencies are allocated to KWL for completion.

8.4. Is portable appliance testing carried out:

HCC provide residential flats unfurnished, therefore no electrical appliances are included within the tenancy agreement. There is no control over the use of residents' own electrical equipment within the flats themselves, however, residents are provided with a tenants' handbook which covers electrical safety.

Whilst portable appliance testing (PAT) is not a legislative requirement, it is a requirement of Health and Safety at Work legislation under the Electrical at Works Regulations 1989, to periodically check electrical equipment for safe use. Any item which is connected to the main supply falls under Regulation 3 & 5 which places a legal responsibility on the owner, as the duty holder, to ensure that all supplied electrical equipment used within the property is safe and not in a position where they may cause danger to staff or residents.

8.5. Is there a suitable limitation of trailing leads & adapters; and without evidence of overloading?

 \checkmark

8.6. Are electrical service cables adequately supported?

Service cables traverse along escape routes within conduit and are adequately supported by metal connections which prevent them from drooping or falling in the event of fire.



Photo 13

Photo 14

Photo 15

All cabling and conduit should be either encased and/or supported by metal connections preventing them to droop or fall. (BS 7671:2018 18th Edition IET regulations), Chapter 52 reg 521-10-202 18th edition).

8.7. Are photovoltaic panels (PV) installed?

None.

Is suitable maintenance is carried out on PV system in line with manufacturers instructions. Is the location of inverters indicated on plans and are there are adequate provisions in place to mitigate the risk of ignition. Is information on PV systems held within the Secure Information Box and accessible to the Fire Service in the event of an incident.

8.8. General comments/defects:

All satisfactory.

Flats

8.9. Are distribution boards non-combustible to BS EN 61439-3 as per BS 7671:2018 (18th Edition IET Regulations) Chapter 42 Regulation 421.1.201(i)?

Yes.



Photo 16

8.10. Are fixed installations periodically inspected and tested?

Samples taken within Flat 12 in the previous assessment (expiry 03/28) gave satisfactory test frequencies.

Inline with BS 7671:2018 IET Wiring Regulations (18th Edition) rented accommodation (flats) with short term leases are periodically inspected every 5 years and upon change of occupancy.

8.11. Are Electrical Installation Condition Report (EICR) labels displayed to indicate the date of the most recent periodic inspection and the date of the next 5-year periodic inspection?

Yes.

8.12. General comments/defects:

All satisfactory.

9. Smoking

9.1. Are there suitable arrangements for those who wish to smoke?

Given the general needs occupancy, there is little HCC can do on a daily basis to control/prevent smoking within residents' dwellings other than raising awareness and highlighting consequences of inappropriate discarding of materials.

There are no smoking receptacles provided externally to the premises, therefore there are no provisions for disposal. Experience at similar buildings has shown that providing smoking receptacles has brought additional problems therefore, given the limited number of discarded cigarettes externally, it is considered to accept the current situation and not install smoking receptacles.

9.2. Are "No smoking" signs provided within the common areas?

The building complies with current no-smoking legislation with signage displayed prominently throughout the building at all levels. Signage displayed is clearly visible and complies with the Smoke Free (signs) Regulations 2012.



Photo 17

9.3. Are reasonable measures taken to prevent fires as a result of smoking?

Residents are permitted to smoke within residential flats, however information relating to smoking is contained within tenants' handbooks.

9.4. General comments/defects:

During the assessment, a comprehensive inspection was carried out in all areas; all internal and external areas were sterile.

10. Arson, security & housekeeping

10.1. Does basic security against arson by outsiders appear reasonable?

The premises has the following arrangements in place:

- Access doors are provided with resident access controls

- External floodlighting is provided by streetlights

- The caretaker is a visual presence and carries out daily inspections on the premises - where necessary significant findings are reported to senior management

- There is a steel security fence which runs along a large percentage of the perimeter of the block; provisions are considered to be an additional physical barrier that makes trespassers think twice about gaining entry - its intention is not to guarantee security

- Hull City council employees require key fobs for access and all contractors require permission before access is authorised

- CCTV is installed internally and external to the building, although it only covers the ground floor, lifts and surrounding areas to the building



Photo 18

Photo 19



Photo 20



Photo 21

10.2. Is there history of / signs of anti social behaviour?

Physical evidence of antisocial behaviour within the block were limited to minor graffiti and the overall condition of internal fixtures and fittings was to a good standard.

Historically blocks of flats are often subject to damage and arson due to the volume of people (general needs) within the building, therefore arson/anti social behaviour will always be a credible threat.

Following liaison with HCC representatives and knowledge of the local area, many of the high rise blocks within the city have been subjected to anti social behaviour, Block 1 is no exception to this.

10.3. Is there an absence of unnecessary fire load in close proximity to the premises or available for ignition by outsiders?

The immediate area around the building was sterile; waste bins were contained within the refuse chute area which is enclosed in a roller shutter and walkways around the block were sterile. Additional waste bins were visible, however they were located clear of the main building and chained to an immovable structure.



Photo 22

10.4. Are escape routes sterile and free from excessive fire loading?

The block operates a specific zero tolerance approach to housekeeping which is backed up by comprehensive signage as all communal areas are sterile. It was confirmed that one of the roles of the caretaker was to continuously monitor areas and should be commended for the standard of housekeeping both internally and externally.

10.5. Is the standard of housekeeping within ancillary accommodation acceptable?

All satisfactory.

10.6. Describe arrangements for the handling and storage of waste:

It is understood that the main bins are emptied through local authority contact on a regular and continual basis. Any additional build up of waste is removed on an ad-hoc contractual basis via HCC waste management. All large waste items collected by the caretaker are stored in the waste compound and where possible out of site from passers by.

10.7. General comments / defects:

All satisfactory.

11. Heating system

11.1. Description of heating for communal areas:

There are no heaters within communal areas/means of escape.

The gas boiler room is located externally at Valiant Drive and serves all three blocks. The boiler is subject to maintenance with records held electronically.







Photo 25

11.2. Description of heating for flats:

Heating within flats is provided by gas central heated radiators.

12. Cooking arrangements

12.1. Description of kitchen layout and arrangements:

There are no cooking facilities within common areas or in ground floor areas where Hull City Council employees operate.

As stated previously, residential flats are provided unfurnished. As a result, HCC are not liable for routine test, inspection and maintenance of appliances. Fire safety information relating to kitchen safety and electrical safety is included within tenants' handbooks.

Kitchens are provided with notional FD20 doorsets, heat detection and cooking facilities are remote from the entrance door and do not prejudice the escape route from any point in the flat other than the lounge.



Photo 26

12.2. Are reasonable measures taken to prevent fires as a result of cooking?

It is considered that HCC are doing all that is reasonable to prevent incidents involving fire from occurring within flats.

13. Lightning

13.1. Does the building have a lightning protection system?

Valiant Drive Block 1, 2 & 3 are the tallest structures in the immediate vicinity and with the projected climate change and increased likelihood of more frequent thunderstorms, the protection of the building as a business and community asset is essential.

Risk against lightning strikes should also include the potential for loss of life and cognisance should also be given regarding the property as sleeping accommodation for circa 96+ individual residents.

It was confirmed verbally and via physical inspection that a lightning protection system (LPS) is in place.



Photo 27

13.2. Has a suitable and sufficient risk assessment (RA) in accordance with BS EN 62305-2:2012 been carried out?

Without any specification to observe, HCC should confirm whether an appropriate assessment of lightning protection has been completed.

The RA would determine if protection is required, the RA should be accurate and site specific. The RA would be measured against:

Sources of Damage:

Lightning current is the primary source of damage, the following sources are distinguished by the strike attachment point:

S1: Flashes to a StructureS2: Flashes near a structureS3: Flashes to a lineS4: Flashes 'near' to a line

Types of Damage

Types of damage which may occur as a result of lightning strikes:

D1: Injury to living beings, due to touch and step voltage - electric shock D2: Physical damage (fire, explosion, mechanical destruction, release of chemicals) due to lighting effects including sparking D3: Failure of electrical and electronic systems due to LEMP

BSEN 6235-2:2012

R: $_1$ Risk of loss of human life R $_2$ Risk of service to the public R $_3$ Risk of loss to cultural heritage

Private & confidential

R 4 Risk of loss of economic value

13.3. General comments / defects:

None.

14. Hazards introduced by outside contractors and building works

14.1. Is there satisfactory control over works carried out in the building by contractors?

HCC has its own maintenance personnel which are generally used for basic and low risk maintenance activities, however where required, (specialist projects) HCC use approved contractors which have completed a comprehensive due diligence process - KWL.

KWL generally act as the principle contractor for works such as fire door replacement programmes and passive fire stopping works.

Like any building, Valiant Drive blocks require maintenance during the lifecycle of their use, it is therefore likely to be subject to external maintenance by contractors requiring the use of hot works. Such activities should be subject to specific control measures such as a 'Permit to Work' (PTW) system. The PTW system allows effective control and supervision of externally introduced ignition sources.

PTW's should be the responsibility of an appointed person from HCC and accountable to the works, content of the PTW should include:

- Scope of hot works
- Time and duration of works
- Area of works
- Competence of contractors
- Correct and maintained equipment
- Pre and post fire sweeps

15. Hazardous substances

15.1.Are the general fire precautions adequate to address the hazards associated with dangerous substances used or stored within the premises?

Following this assessment, there were no process risks or situations identified which required any assessment under the dangerous substances and explosive atmospheres regulations (DSEAR) 2002.

Residents are prohibited to use portable paraffin or gas cylinder heaters.

Information relating to dangerous substances and materials should be included within the tenants' handbooks.

15.2. Other significant fire hazards that warrant consideration?

It has been confirmed that some residents engage in substance misuse; such activities significantly increase the risk of fire within the property as not only does it introduce ignition sources but there is also the potential for residents to be under the influence which will affect response and acknowledgement of an incident.

16. Cladding & wall coverings (spread of flames and fire)

Design and materials of external walls

Regulation 5 Fire Safety (England) Regulations 2022: The responsible person in relation to a high-rise residential building must prepare a record of the design of the external walls of the building, including details of the materials from which they are constructed.

The record prepared must include details of the level of risk identified in the risk assessment required under article 9 of the Regulatory Reform (Fire Safety) Order 2005 that the design and materials of the external walls give rise to and any mitigating steps that have been taken in respect of that risk.

The responsible person must prepare a revised record if there are any significant changes to the external walls of the building.

16.1. Do the external walls of the building adequately resist the spread of fire over the walls and from one building to another, having regard to the height, use and location of the building?

Since the point of construction, the premises has undergone several cycles of refurbishment, one of which included the installation of a partial cladding / external wall system.

Following the Grenfell Tower tragedy, HCC commissioned UK LPP to complete a series of surveys on external cladding and external wall systems to HRBB's across Hull in 2017. Although findings of surveys confirmed that external walls systems met the functional requirements of Building Regulations and did not contain ACM's, reports provided limited information and potentially fall short of today's benchmarks for a PAS 9980 external wall survey.

Taking into consideration developments within the sector surrounding external wall systems, Holistic Fire Safety feel it would be prudent to undertake further surveys to confirm provisions. Surveys will provide assurances to the Building Safety team that external wall systems are compliant without exposing occupants to unnecessary risk.

Decision making has been further justified as HCC now have a dedicated BSM and Building Safety team who have realigned their objectives which a specific focus on external walls and fully understanding the structural make up of premises.



Photo 28

16.2. Is there a requirement for an External Wall Fire Risk Assessment to be carried out in line with PAS 9980?

Holistic Fire Safety have completed an external wall construction assessment which has determined the requirement for an External Wall Fire Risk Assessment to be carried out in line with PAS 9980.

16.3. Are records of the design of the external walls and details of the materials from which they are constructed readily available?

Basic records of external walls and lightweight cladding systems are held by HCC, however as detailed above there are potentially shortfalls in information; therefore, Holistic Fire Safety have advised an External Wall Fire Risk Assessment to be carried out in line with PAS 9980.

16.4. General comments / defects:

The external envelope of a building is not expected to contribute to undue fire spread from one part of a building to another part. This is also achieved by the following;

• The risk of ignition by an external source to the outside surface of the building and spread of fire over the outside surface is restricted by a strict housekeeping policy; and

• The materials used to construct external walls, attachments to them, and how they are assembled do not contribute to the rate of fire spread up the outside of the building.

Previously there has been no specific reference within the Fire Safety Order (FSO) 2005 to external wall systems and fire doors; however, for clarity they are now specifically mentioned within the Fire Safety Order: Article 6 – 'Application to premises'.

the FSA 2021	1 makes amendment to article 6 of the Fire Safety Order 2005
1 Prem	ises to which the Fire Safety Order applies
In article 6	s of the Regulatory Reform (Fire Safety) Order 2005 (5.1. 2005/1541) (application to premises)
	s paragraph (1)(a) (excluded premises), after "except to the extent mentioned in" insert "paragraph (1A) or" ther paragraph (1) insert –
"(1A) When	re a building contains two or more sets of domestic premises, the things to which this
order	applies include-
(a) the	e building's structure and external walls and any common parts;
(b) All	doors between the domestic premises and common parts (so far as not falling within sub-paragraph (a)).
(1B) The re	eference to external walls includes
(a) Do	sors or windows in those walls, and
(b) Ar	whing attached to the exterior of those walls (including balconies).";
(c) In	paragraph (2), for "paragraph" substitute "provisions"

Photo 29

Internal Surface Linings

16.5. Do surface linings within the building contribute towards fire growth?

Escape routes at Block 1 are protected through effective compartmentation of REI 30 and the majority of surface lining materials are furnished to Euro Class B- s3, d2 or better to inhibit any lateral fire spread.

All linings of internal walls and floors within protected areas are solid and non combustible, and free of any additions which could be ignited and contribute to surface flame spread.

As a result, surface linings on walls and floors are not expected to contribute towards fire growth.

Protected escape routes should be protected through effective compartmentation of REI 30 with all surface lining materials furnished to Euro Class B-s3, d2 or better to inhibit any lateral fire spread.

16.6. General comments / defects:

The ceiling of the ground floor reception has ceiling tiles which are typical of those found within other HCC blocks; these tiles are suspected to be of a combustible nature. Although there is a concrete slab which separates floors, should tiles be subjected to ignition, it is foreseeable that they would contribute towards fire growth; as a result and as a low priority action, tiles should be removed / enclosed.



17. Compartmentation & Fire Separation

The appropriate fire separation and compartmentation of parts of a building are designed to restrict the internal spread and inhibit the damage of fire. This usually takes place between floors/ceilings and rooms/areas of high risk, with the creation of 'designated' or 'protected' routes whereby occupants can make their escape relatively unhindered and unharmed.

17.1. The fire resistance of the structure is as follows:

As per current statutory guidance, the following fire resistance levels are expected for the building:

- 120 minutes: for structural load-bearing elements
- 120 minutes: All compartment walls other than between any flat or firefighting stair, lobby or shaft
- 60 minutes: Separation between residential flats and any other area
- 30 minutes: for all protected escape routes within communal areas

17.2. Are there clear and obvious breaches / defects in fire resisting construction?

Protected escape routes and residential dwellings are generally well compartmented with little to no evidence of breaches/defects which could result in injury/ill health of relevant persons however, digital tv cables have penetrated the compartment floor to all levels from the first floor to the lift motor room in the west side staircase lobby.

As the majority of services which supply flats exit horizontally into service risers, should a flat fire occur, the likelihood of it affecting neighbouring dwellings (horizontally and vertically) is remote.

There are multiple defects within service risers where services are not adequately fire stopped as they enter adjacent compartments.

It is not reasonable to identify and advise on remediation for every breach / defect in compartmentation (fire stopping issues) that might exist within a building. Where defects are consistent and it is foreseeable that defects have the potential to affect the safety of those within the building, a specific compartmentation survey should be undertaken. The key principles of a compartmentation survey are to identify routes of heat and smoke transfer within the premises, e.g. service risers, ventilation risers, kitchen and bathroom extraction arrangements, flat entrance doors and breaches in fire resisting construction. The survey should determine whether past alterations / refurbishment on the building have had an impact existing compartmentation.

17.3. Is a compartmentation survey required / been carried out on the premises?

As part of the T4 fire risk assessment project, Holistic Fire Safety completed a compartmentation survey on each HRRB. Holistic Fire Safety has appraised the compartmentation of each building and subsequently identified all breaches and defects in fire resisting construction.

HFS's passive fire protection installers who work under the BM Trada Q-Mark scheme have identified each individual penetration and plotted them onto the building layout plans. Each report has identified the surface, substrate and size of each penetration before providing examples of materials which could be used to remediate.

Holistic Fire Safety have provided HCC with methods of satisfying building regulations, and with the intention of complying with test details, supplied by 'Protecta' and other manufacturers.

HCC have submitted the reports to the Building Safety Regulator for approval.

As all properties are existing buildings, and are to remain occupied for the duration of remediation, it may not always be practicable to install a tested solution; therefore, the principle of 'betterment' and to the 'intention of' will be applied. Refer to: HFS.HCC.ValiantDrive1.CSR.1.0 - Executive Summary & Bolster pin drops

Summary of findings from compartmentation survey

17.4. Flats:

No obvious defects present.

Fire dampers are present within ventilation extracts within the bathroom of flats.

At the point services pass into adjacent service risers, fire stopping should be carried out from within risers using tested single sided details supplied by third party certified manufacturers and installers.

17.5. Common Areas:

Digital tv cables have penetrated the compartment floor to all levels from the first floor to the lift motor room in the west side staircase lobby.

Breaches were present at the point data cables and conduit pass through fire resisting partitions. The majority of these appear to have been fire stopped although there was no test evidence to support this.



Photo 31







Photo 32





Photo 33



Photo 36

17.6. Ancillary Accommodation:

The standard of compartmentation within the water pump room and lift motor room was generally satisfactory with limited evidence of breaches - minor works required however, there is a significant penetration in the pump room where services travel into the adjacent flat (2). It is understood this was created as a result of the replacement of the flat entrance door.

The cleaners cupboard on the ground floor contains cable bundle penetrations. It was noted there are two air transfer grills (ATG) within the cleaners cupboard that pass through the compartment wall into the ground floor staircase. Upon inspection, it is not clear if these are intumescent ATG's. HCC should confirm that the ATG's are intumescent.

HCC should refer to the compartmentation survey for evidence of breaches and methods of remediation.



Photo 37



Photo 40



Photo 43

17.7. Service Risers:



Photo 38



Photo 41








Photo 42

There are x2 service riser shafts within the building which are partially compartmented at all floor levels creating x24 enclosures. Following comprehensive inspections and sampling, breaches/defects are extensive and consistent throughout all areas.

As previously described, the majority of services (soil vent pipes, heating pipework, data cables etc) which supply flats pass freely between risers and dwellings without an effective sealing system in place.

Example breaches consist of:

- Non compliant air transfer grills at the head of service riser doors
- Non compliant fanlights at the head of service riser doors
- Services passing through service riser fanlights without appropriate fire stopping in place
- Combustible plastic pipework entering risers from flats without an effective closing device present.

- Combustible plastic pipework which travels vertically from riser to riser without an effective closing device present.

- Insulated non combustible pipework travelling vertically from riser to riser without an effective closing device present.

- Non combustible pipework entering risers from flats without an effective sealing system
- Linear gaps between door frame and substrate and door heads have been filled with polyurethane expanding foam (this is not a suitable/tested solution for backfilling around timber doorsets).

All compartments gave evidence of excessive use of pink polyurethane expanding foam. Most Polyurethane foams are combustible, which means they offer limited fire-stopping properties. Best practice states 10mm and 33mm, (spaces such as bed and side joints to lintels and frames). That polyurethane based foams should not be used unless in limited spaces between. This filler does not protect larger spaces as it will never achieve satisfactory fire-resistant results. Any PU foam products used must have any fire safety performance determined by testing, to standards BS 476 Part 20/22 and BS EN 1366-4 for linear gaps and BS EN 1366-3 for service penetration seals.

Remediation will primarily consist of sealing defects with an ablative coated fire batt and mastic system applied in conjunction with an intumescent wrap/fire collar for combustible pipework.

Where annular gaps allow, all isolated non combustible services can be sealed using fire rated mastic which is tested to BS EN 1366-3/4 and classified to 13501-2:2017 + A1:2009.

HCC should refer to the compartmentation survey for evidence of breaches and methods of remediation.



Photo 45



Photo 48

17.8. Ventilation Risers:

None.

Extract ducting within bathrooms have fire dampers installed which are activated by fusible link.

17.9. Other:

Refuse chutes are self contained with no obvious signs of breaches.

Conclusion

17.10. Are levels of compartmentation within the building adequate to separate adjoining flats, flats and the common areas and flats and other ancillary accommodation?

No O&M manuals have been supplied to HCC following previous fire stopping works.

HCC representatives confirmed that current fire stopping measures were carried out as a temporary control measure following initial concerns in a previous assessment; works were not carried out by a third party



Photo 46



Photo 47

certified installer. It was confirmed that all future fire stopping works are to be completed by competent third party certified installers following findings of the compartmentation survey.

It can be confirmed that as services travel horizontally into service risers and not horizontally or vertically into neighbouring residential flats; although defects and breaches are present, they are not expected to affect the safety of relevant persons due to the evacuation strategy being stay put.

Providing passive fire protection works are undertaken within a timely manner, using tested solutions and completed by a third party certified installer, levels of compartmentation are considered satisfactory to support the evacuation strategy and its occupancy.

HCC must ensure that handover packs are received from contractors undertaking works to meet the requirements of Building Regulations 2010 - Regulation 38 - Fire Safety Information.

18. Means of escape from flats

18.1. Description of flat layout:

Residential flats are single and two bed occupancies whereby all habitable rooms discharge onto the internal hallway.





Photo 49

Photo 50


18.2. Are travel distances within flats restricted to 9 meters? If distances exceed tolerances, are mitigation measures in place adequate to control the risk?

The maximum travel distance within flats is 10m.

Means of escape within flats is typical of diagram 3.3 of ADB B1 which does not require flats to have a protected internal hallway. This principle was based on limiting travel distances to circa 9m which in turn reduces the chance that residents could become trapped in the event of a fire. Additionally, cooking facilities are remote from the entrance door and do not prejudice the escape route from any point in the flat.

Although the travel distance is slightly in excess of 9m, automatic fire detection and warning is provided within the primary risk room (kitchen) and throughout escape routes including the lounge; in addition, existing doors to the lounge and kitchen are notional FD20 doors with Georgian wired toplights - both of which are expected to be adequate to provide sufficient time for evacuation.

(Creating a protected route within flats in an occupied legacy building is considered unreasonable given challenges with access, distress to residents and additional works created by the install within properties etc - In addition, should doors be replaced, they would not require a closer and therefore would remain open given the occupancy profile, therefore no benefit would be achieved for the time/money/effort carried out).



ADB B1 Diagram 3.3 Photo 51

18.3. Are flats provided with a protected entrance hall and restricted travel distance? Is the standard of doors and construction adequate to restrict fire growth and facilitate evacuation from the dwelling?

As described above, there is no requirement for the entrance hall to be a protected route as travel distances are acceptable given the level of fire detection and that flats are provided with 30-minute fire-resisting construction and 20-minute fire-resisting doors.

18.4. Are flats provided with an alternative exit?

No.

18.5. Are further mitigation measures required as a result of defects / non compliant provisions?

Provisions within flats appear to be satisfactory to ensure the safety of residents.

19. Means of escape from common parts

19.1. Are flats provided with a balcony approach or deck approach?

No.

19.2. Are flats provided with a corridor or lobby approach?

Yes.

19.3. Is every flat is separated from the common escape stairway?

Every flat is separated from the common escape stairway by a protected lobby created by a minimum of x2 self closing notional fire resisting doors.

Ground floor flats discharge directly into the building reception, however alternative means of escape are provided to both the front and rear of the property.

19.4. Are there reasonable distances of travel where there is escape in a single direction?

The distance of travel between the flat entrance door and the door to the lobby is limited to 4.5m.

19.5. Are there reasonable distances of travel where there are alternative means of escape?

The ground floor is provided with alternative exits, both of which are within reasonable distances and are separated by fire resisting construction.

19.6. Are there adequate smoke control provisions to protect the common escape routes?

Lobbies on all floors are provided with both manual and permanent ventilation. Ventilation is provided by louvered vents and manual openable windows with restricted openings.

Current guidance states that vents in lobbies or corridors adjoining single stairways should be operated automatically (AOVs), however the installation of AOV's are not considered reasonably practicable. In addition, although current openings do not provide a minimum free area of 1.5 metres squared (m2), current provisions are considered adequate given other mitigation measures in place.

Protected stairways also need means to ventilate any smoke that may enter the stairway during evacuation or fire fighting and allow a route for air to reach ventilated lobbies. A vent of at least 1m2 needs to be provided at the head of the stairway for this. Current guidance states that in blocks of flats with a single stairway, it is recommended that the vent is operated automatically via an AOV.



Photo 52

19.7. Are door widths and escape routes are sufficient for the volume of occupants who are required to use them?

Door widths along escape routes are considered to be satisfactory for the evacuation strategy and occupancy.

Approx. widths which form part of the escape route are as follows;

- Stair 1060mm (900mm Inc. handrails)
- Lobby doors between 770-800mm
- Final exits 800mm

There is currently no recorded evidence of challenges faced by residents with regards door widths.

19.8. Do doors along escape routes in the direction of escape, where necessary?

All doors open in the direction of travel where necessary.

19.9. Do escape routes have a minimum clear headroom of 2m and are escape route floor finishes designed to minimise their impact when wet?

Floor coverings and head clearances are adequate to assist with evacuation.

19.10. Are all routes are clearly identified through appropriate signage and lighting which lead residents to a place of ultimate safety?

Provisions for signage and emergency lighting are considered to be adequate to aid and assist relevant persons reach a place of ultimate safety.

19.11. Are there adequate provisions of exits which are easily and immediately openable?

Final exits doors are manually operated via single action mechanisms and fail safe to open in the event of power failure.

19.12. Is the fire-resisting construction (including any glazing) protecting escape routes and staircases of a suitable standard and maintained in sound condition?

Escape routes are suitably separated and subdivided by fire rated construction which is made up of notional self closing FD30s door assemblies and Georgian wired glazing. Partitions are made up of brick and blockwork. Current provisions are considered adequate to protect means of escape.



Photo 53



Photo 54



Photo 55



Photo 56

19.13. Is the design and maintenance of the means of escape considered adequate?

The general principles of means of escape applied at Block 1 are:

- Horizontal escape from the flat entrance door to a stairway or final exits; and

Vertical escape via a stairway leading to a final exit or place of relative safety
Corridors and escape routes are clear of significant fire hazards, meaning that the most likely place for a fire to start is within a flat;

- Flats and risk rooms have a reasonable level of compartmentation; therefore, the probability of fire spread from the room of origin will be low; and

- If a fire does occur in common areas, the materials and construction will restrict fire spread and development whilst additional measures are in place to raise the alarm and provide smoke control.

20. Fire Doors

20.1. Is the fire resistance of doors / curtain walling to staircases and the common areas considered adequate, and are the doors maintained in sound condition? Describe the standard and condition of door sets?

As detailed previously every flat is separated from the common escape stairway by a protected lobby. All doors which form part of escape routes are self-closing, notional FD30 fire doorsets which are considered to be in good condition considering their age and usage; however general maintenance and remediation is required.

It is expected that current installations are satisfactory and will prevent the passage of smoke and products of combustion which could compromise escape routes.

Doorsets are provided with:

- Good condition notional leaf and frame
- · Good condition polished Georgian wired integrity fire resistant glazing
- x3 100mm hinges
- Frames have a 25mm stop lat
- Appropriate single strip combination cold smoke and intumescent seals fitted into the leaf

Gaps between leaf and frame are generally not more than 3mm top and side rails, however there are variations to this and gaps at the bottom threshold are consistently >8mm and will require attention
A BSEN 1154 CE marked self closing device with a minimum power rating 3 (Grade 1) is fitted to all communal doors. A number of samples were taken on different floors with the majority capable of closing from any angle and not taking longer than 25 seconds to overcome the resistance of any seals to close into their frames.

Defects consisted of:

• Painted hinges requiring replacement

• Strips and seals are consistently over painted and occasionally routered too deep (although gap tolerances are negligible which generally enable brush seals to sit against the frame)

As a result, given minor defects, a specific fire door inspection is to be undertaken to specify what actions are required.



Photo 57





Photo 58

Photo 5

20.2. Is the fire resistance of doors to meter cupboards/store rooms/plant rooms in the common areas considered adequate, and are they adequately secured and/or fitted with suitable self-closing devices? Describe the standard and condition of door sets?

As detailed previously many of the risers doors have large air transfer grilles within them and others have fanlights which are made up of inappropriate fire resisting construction.

Should a fire occur within the area, products of combustion could pass freely into the means of escape. Although, the block employs a stay put policy, unless enclosures require ventilation, it is possible that unnecessary smoke logging of the area directly outside flats could occur. Findings are generally consistent on all residential floors. Service riser doors are notional FD60s fire doorsets and they do not provide adequate separation to protect means of escape. Current doorsets are timber 54mm notional doorsets hung by x3 steel hinges which lack BS markings. Both the leaves and frames display evidence of defects, strips and seals are painted over and gaps are generally excessive. Air transfer grills also don't appear to be intumescent lined meaning that there is little to no compartmentation in place.

In addition services also pass through grills confirming their use as unsuitable. Findings are consistent on all residential floors. There was evidence of a lack of backfilling/fire stopping between the frame and substrate.

HCC have reviewed ventilation requirements for riser doors with a specification drawn up which has been submitted to the Building Safety Regulator for approval.



Photo 60



Photo 63



Photo 66



Photo 61



Photo 64



Photo 62



Photo 65

20.3. Are suitable self-closing devices fitted to doors which discharge into common areas?

All doors other than those locked shut which form part of, and discharge onto escape routes are provided with overhead, scissor self closing devices.



Photo 67

20.4. Is the fire resistance of flat entrance doors considered adequate, and are doors maintained in sound condition? Describe the standard and condition of door sets?

All flat entrance doors have been replaced with third party certified FD30s fire doorsets, which meet the requirements detailed in the ADBVol: 1 Appendix C1 2a for fire resistance and smoke control from both sides, and are fitted with an appropriate positive action self-closing device (BS 1154) and a single action mechanism which does not require the use of a key.

No evidence of certification has been provided, however handover packs are expected to be held by HCC compliance teams.

Door-sets have BM Trada Manufacturers plugs installed within the edge of the door leaf, however there is no evidence to suggest that doorsets have been installed by BM Trada certified installers.







Photo 69

20.5. Are suitable self-closing devices fitted to flat entrance doors and, where fitted, maintained in good working order?

All flat entrance doors are fitted with an appropriate overhead BS 1154 self closing device.



Photo 70

21. Means of warning

21.1. Is a fire detection and fire alarm system provided within the common areas of the building? Where applicable, confirm the category of system and describe provisions.

Block 1 does not have a communal fire alarm system, nor is one considered necessary given its occupancy and preventative and protective measures in place.

The boiler room at Valiant Drive is provided with automatic detection which is a P1 fire alarm system which meets the standards detailed in BS 5839-1.



Photo 71

21.2. Where applicable, is control indicating equipment provided and positioned in a suitable location?

Yes.



Photo 72

21.3. Where applicable, has a fire alarm zone plan been provided? This should consist of 'a diagrammatic representation of the building, showing building entrances, the main circulation areas and the division into zones. The diagrammatic representation should be printed, correctly orientated and provide an accurate zone plan.'

No. It is not considered necessary to provide a fire alarm zone due to the simple layout of the building i.e. one room.

21.4. Where applicable, are manual call points provided at suitable locations? Describe provisions.

Manual call points are fixed at a height of approximately 1.4 metres above finished floor level and are easily accessible.



21.5. Where applicable, are sounders including visual alarm devices suitable for the occupancy and considered adequate in raising the alarm?

Yes.



Photo 74

21.6. Where applicable, is the system connected to an alarm receiving centre?

Yes.

21.7. Where applicable, are there adequate arrangements in place for silencing and resetting an alarm condition?

Yes.

21.8. Are provisions within communal areas adequate to meet the purpose group and occupancy of the building?

Yes.

Detection and alarm systems within residential accommodation

21.9. Are provisions within residential accommodation adequate to meet the purpose group and occupancy of the property? Describe the standard/category along with provisions.

Each residential flat is provided with a Grade D1 LD2 (BS 5839:2019 + A1:2020) system which comprises of smoke detection throughout all circulation areas that form part of the escape route from [within] and heat detection within areas of high fire risk to occupants (kitchen).

Upon activation of a detector, the alarm will sound locally to the flat of origin and it will be the responsibility of occupants / neighbouring residents to notify Humberside Fire & Rescue to request their attendance. Actions to be taken are confirmed by Fire Action Notices and information contained within residents' handbooks.

Residents with specific impairments should be provided with individual devices in the form of pendants and

vibrating pads. Again, such provisions should be considered as part of the PCFRA.

HCC confirmed that as part of future proofing of their HRRB's, as a baseline install within void properties, a Grade D1 LD2 fire alarm system is installed. HCC are also working on a system which sends key information to the cloud. e.g. the system will identify issues in the event of an activation - HCC will be automatically notified. HCC do not currently have sufficient resources to monitor activations however, plans are being put in place to achieve this.







Evacuation alert system

Inline with recommendations made in Phase 1 of the Grenfell Tower report (Executive Summary) Section 12, 33.22 (d). If the property is defined as a high rise residential building, it should be equipped with an evacuation and alert system which meets BS 8629:2019.

- 21.10. Is an Evacuation alert system provided and does it consist of the following:
- Evacuation and alert control indicating equipment (EACIE) within additional SIB accessible
- to the attending Fire and Rescue Service
- Signage to indicate EACIE
- Sounders for evacuation and alert system within each residential flat
- EACIE to be on toggle switches
- Ability for the Fire and Rescue service to control evacuation by individual floor or whole building

There is no evacuation alert system provided at Block 1.



22. Emergency escape lighting

22.1. Has a reasonable standard of emergency escape lighting been provided? Is emergency escape lighting adequate to enable occupants to locate, and move safely along defined routes and escape via final exits? Describe arrangements and deficiencies observed.

Although emergency lighting was not tested, an inspection of luminaires and their locations has determined that provisions are adequate to enable occupants to locate, and move safely along, defined routes and escape via final exits.

Emergency lighting installed consists of wall and ceiling mounted luminaires which are located directly outside flats, lobbies and the stairwell; all luminaires are low voltage LED.

The building is provided with a mixture of maintained (X 1 180) luminaires and non maintained (X 0 180) luminaires with a three hour battery back up. Final exits are maintained units. Internal and external provisions appear satisfactory, although there are some small rooms such as the cleaners store which are not provided with luminaires, however based on risk assessment, the risk within these areas has determined current provisions as satisfactory.

Luminaires are provided with test switch keys which are located at various places and are tested monthly internally.

Provisions appear to be in accordance with BS 9999 Table 8

Table 8	Provisions for emergency escape lighting	
	Occupancy characteristic	Areas needing emergency escape lighting
	A	Underground or windowless accommodation
		Stainways in a central core or serving storey(s) more than 18 m above ground level
		Internal corridors more than 30 m long
		Open-plan areas of more than 60 m ²
	B AI	All escape routes ⁽⁰⁾ (except in shops of three or fewer storeys with no sales floor more than 280 m ² provided that the shop is not a restaurant or bar)
	c	All common escape routes ¹⁰ , except in two-storey blocks of flats
	Any use	All sanitary accommodation with a floor area over 8 m ²
		Windowless sanitary accommodation with a floor area not more than 8 m ²
		Electricity and generator rooms
		Switch room/battery room for emergency lighting system
		Emergency cantrol room
	In areas of shops where the public are not admitted use occupancy characteristic A.	
	³⁰ Including external estape routes.	

Photo 80

The second second



Photo 81



Photo 82



23. Fire safety signs and notices

23.1. Is there a reasonable standard of fire safety signs and notices?

Fire safety signage is generally to a satisfactory standard both internally and external to the premises with reasonable provisions for hazard warning signs (risk rooms), mandatory signage for fire doors, information signage detailing emergency arrangements and prohibition signage for smoking. Fire safety signage is generally in accordance with the Health and Safety (Signs and Signals) Regulations together with BS 5499-4: 2013 and BS EN 7010.

23.2. Are Fire Action Notices provided and displayed in appropriate locations?

Residential floors are provided with comprehensive instruction on actions to be taken in the event of fire. Fire action notices are displayed prominently opposite/adjacent lift doors although fire action notices were missing on floors 8, 10 & 11.





Photo 84

Photo 85

23.3. Is emergency evacuation/safe condition signage provided within communal areas?

Due to the single means of escape, and the expectation that all residents are familiar with the layout of the building, although some signage is technically incorrect in places (lobby doors with down arrow), current safe condition signage provided is considered to be satisfactory and it is expected that all relevant persons using the building will understand signage in place.

Should changes be made to escape route layouts, it is advised that escape route signage consists of the following:

• A combination of a BS EN ISO 7010 emergency exit sign including a directional arrow and supplementary text

• The use of supplementary text should be in accordance with BS 5499-4 clause 4.7 and state either 'Exit' or 'Fire Exit'

• For any sign suggesting a 'straight ahead' an up arrow is required (meaning 'progress forward and through here' as per BS 5499-4:2013 Table 1). A down arrow suggests a change in level downwards.

It is advised that all replacement safe condition escape route signage should be photo luminescent as manufactured by Jailite. Signs should be rigid or semi rigid PVC fixed by 4 x screws in each corner of the sign or with appropriate adhesive.



Photo 86

23.4. Is suitable and adequate signage in place to notify relevant persons of actions taken in relation to lifts?

Information relating to the use of lifts in the event of fire is contained within fire action notices.

23.5. Is 'Fire exit, keep clear' signage in place at appropriate locations?

To prevent persons from obstructing emergency exit doors on the external side of the building, 'Fire exit keep clear' signs that comply to BS 5499-4 have been displayed on the outside of final doors.

23.6. Is hazard warning signage provided at appropriate locations?

Hazard warning signage is in place on the external face of risk areas such as the lift motor room and the external electrical substation. Each individual ESU within the building is also provided with hazard warning signage to warn both occupants and responding fire crews.



Photo 87

23.7. Is mandatory signage prescribing a specific behaviour in place at appropriate locations?

Mandatory signage prescribing a specific behaviour is displayed prominently on all fire doors where necessary (including flat entrance doors) throughout the building.

• Fire doors which are accessible from either side have 'Fire door keep shut' signs attached to both sides of the door leaf

• Fire doors where access is restricted, has 'Fire door keep locked' sign to the open facing leaf of the door only

'Fire door keep shut' signs were not displayed on some communal doors.





Photo 89



Photo 90



Photo 91

23.8. In relation to Regulation 8 of the Fire Safety Regulations 2022, has the responsible person ensured that the building contains clear markings of floor identification and identification of domestic premises in the form of Wayfinding Signage?

Wayfinding Signage is installed at Block 1 in accordance with Regulation 8 of the Fire Safety Regulations 2022.

It is a requirement that floor numbers be clearly marked on each landing within the stairways and in a prominent place in all lobbies in such a way as to be visible both in normal conditions and in lowlighting or smoky conditions.

ADB Vol 1. 15.14 states that floor identification signs should meet all of the following conditions:

A. The signs should be located on every landing of a protected stairway and every protected corridor/lobby (or open access balcony) into which a firefighting lift opens.

B. The text should be in sans serif typeface with a letter height of at least 50mm. The height of the numeral that designates the floor number should be at least 75mm.

C. The signs should be visible from the top step of a firefighting stair and, where possible, from inside a firefighting lift when the lift car doors open.

D. The signs should be mounted between 1.7m and 2m above floor level and, as far as practicable, all the signs should be mounted at the same height.

E. The text should be on a contrasting background, easily legible and readable in low level lighting conditions or when illuminated with a torch.

ADB Vol 1. 15.15 states the floor number designations should meet all of the following conditions:

F. The floor closest to the ground level should be designated as either Floor 0 or Ground Floor. G. Each floor above the ground floor should be numbered sequentially beginning with Floor 1.

H. A lower ground floor should be designated as either Floor –1 or Lower Ground Floor.

I. Each floor below the ground floor should be numbered sequentially beginning with Floor –1 or Basement 1.

ADB Vol 1. 15.16 states the flat indicator signs should meet all of the following conditions:

J. The signs should be sited immediately below the floor identification signs, such that the top edge of the sign is no more than 50mm below the bottom edge of the floor identification sign.

K. The wording should take the form Flats X-Y, with the lowest flat number first.

L. The text should be in sans serif typeface with a letter height of at least half that of the floor indicator sign.

M. The wording should be supplemented by arrows when flats are in more than one direction. N. The text and arrows should be on a contrasting background, easily legible and readable in low level lighting conditions or when illuminated with a torch.



Photo 92

For the purposes of the paragraph above "markings" means an identification designed and located in accordance with the

guidance in Volume 1 of Approved Document B(1) on each landing within the stairways and in the lift lobbies of the

floor level marked in such a way as to be visible both in low level lighting conditions or when illuminated with a torch.

24. Extinguishing media and fixed systems

24.1. Is Automatic Water Fire Suppression Systems (AWFSS) provided within communal areas/ancillary accommodation? Where applicable, describe arrangements and deficiencies.

None provided.

24.2. Is Automatic Water Fire Suppression Systems (AWFSS) provided within residential accommodation? Where applicable, describe arrangements and deficiencies.

Cognisance of the structure and use of the building, together with its long term future planning, consideration should be given to the additional protection afforded by engineering solutions such as retro-fitted AWFSS sprinkler system.

The recent amendment to ADB Vol 1. (May 2020) with regard to the lowering of the trigger height for sprinkler requirements in relevant buildings to 11 metres only emphasises this is a proactive approach to the direct safety of the sleeping residents.

24.3. Is suitable portable firefighting equipment provided at appropriate locations? Where applicable, describe arrangements and deficiencies.

Extinguishers are not present within means of escape.

The boiler house is provided with one composite P50 foam extinguisher and a dry powder extinguisher.

The use of dry powder extinguishers within small and under ventilated compartments should be avoided - this principle should be applied across HCC's housing stock.

The use of dry powder extinguishers indoors can lead to:

- impaired visibility

- issues with inhalation
- damage to plant and property

Dry powder extinguishers should be removed and replaced with an appropriate extinguisher.





Photo 94

25. Other relevant fixed systems and equipement

25.1. Where applicable, are there appropriately sited facilities for electrical isolation of any photovoltaic (PV) cells, with appropriate signage, to assist the fire and rescue service?

There is no PV system installed at Block 1.

25.2. Other fixed systems including arrangements and deficiencies.

Fire dampers are provided in ductwork at the point extraction exits bathrooms in residential dwellings and enters central shafts. Bathrooms gave evidence of x2 vents (high/low level) which have dampers installed which are activated via fusible link.

It was confirmed that accessible dampers which are located in service risers are subjected to inspection and testing every four years. As dampers are activated via fusible link, there are no moving parts and therefore no requirement for inspection.



Photo 95



Photo 96



Photo 97

26. Access and facilities for the fire service

26.1. Are the following provisions provided for the premises:

- External access which enables fire appliances to be used near the building
- Access into the building for firefighters to search and rescue people
- Access into the building for firefighters to fight any fires

Access roads are generally free from obstruction and depending on route taken are not compromised by parked vehicles even though surrounding areas are heavily populated by residential accommodation.

HFRS are provided with key fob access and crews regularly carry out familiarisation visits.


In line with Regulation 4 & 6 of the Fire Safety Regulations 2022, Holistic Fire Safety have provided HCC with information to include within the secure information box e.g. accurate building and floor plans to assist HFRS search and rescue people and fight fires.

26.2. Are provisions for fire appliance approach and positioning satisfactory to facilitate and assist emergency response? Describe arrangements and deficiencies - widths, heights, weight tolerances, distance from dry riser/building etc.

Access to Block 1 is via Barham Road and leads directly to the front of the building.

Current provisions provide a minimum of 3.7m in width and 4m in height to allow for unrestricted access for pumping and high reach appliances (ADB Vol 1. B5 Table 13.1).

There are no obvious signs of weight restrictions or anything that could impact appliance approach and positioning. The nearest point at which a fire appliance could position to the building is <18 meters; however as described above the location of appliance positioning will be dynamic and confirmed by the Officer In Charge.



26.3. Water main: Describe arrangements and deficiencies observed.

All immediate hydrants are within 90 metres, and are 100mm diameter and are the responsibility of the local water authority undertaking, via Humberside Fire and Rescue Service, who maintain each hydrant on a two year flow test programme.



Photo 101

26.4. Dry riser: Describe arrangements and deficiencies observed.

There is no dry riser provided at Block 1.

It was confirmed by HCC representatives that all HRRB's which do not have dry riser facilities are scheduled to have one installed. The dry riser is to be installed which serves all floors with landing valves within the lobby between the staircase door, hopper disposal point and louvred windows on all floors.



Photo 102

26.5. Other / defects:

Lifts at Block 1 are not designated firefighting lifts, however there is an agreement in place that lifts would be utilised by HFRS in the event of an incident.

Signage within communal areas clearly states that lifts are not to be used in the event of an incident by relevant persons.

Secure information box

In relation to Regulation 4 of the Fire Safety Regulations 2022, the responsible person in relation to a high-rise residential building must install and maintain a secure information box in or on the building

26.6. Is the secure information box positioned at a location in or on the building which is readily accessible to the fire and rescue authority?

The SIB is located in the main entrance within the ground floor lobby. It has been agreed by all relevant parties that its location is the most suitable - internally.



Photo 103

26.7. Is the secure information box capable of containing documents required by these Regulations and is it reasonably secure from unauthorised access and vandalism?

HCC continuously review the content of the SIB.

Content is to include the following:

- 3 laminated plans of each floor including flat numbers + arrangements to meet Regulation 6
- Details of vulnerable residents PEEPS (Personal Emergency Evacuation Plans)
- Evacuation plan for the block
- Details of "essential fire-fighting equipment"
- Location of utility `shut off` valves
- Location of service risers
- Location of fire fighting lifts (where applicable)
- Location of EACIE (if/when installed)
- Copies of building access keys
- Copies of lift engagement key
- Copy of SSRI & Ops Pre plan
- Copy of appliance pump pressure convertor
- Location of utility `shut off` valves

The responsible person must ensure that the following information is contained within the secure information box (Assessor to confirm)

26.8. Is the name, address and telephone number within the United Kingdom of the responsible person present?

Yes.

26.9. Is the name and contact information of such other persons within the United Kingdom who are provided with the

facilities to and are permitted to access the building as theresponsible person considers appropriate present?

Yes.

26.10. Has the responsible person provided the local fire and rescue authority with everything required to enable it to

access the secure information box and are arrangements in place to as soon as reasonably practicable notify the local fire and rescue authority if there are any changes to those requirements?

Holistic Fire Safety are to complete an audit/assessment of the management of HRRBs - this audit/assessment will confirm HCC are meeting all the requirements of the Fire Safety Regulations 2022.

It can be confirmed that arrangements are in place to notify the local fire and rescue authority if there are any changes which affect their ability to gain access to the building, carry out search and rescue or carry out firefighting operations.

https://humbersidefire.gov.uk/your-safety/business-safety/fser



Floor plan and building plans

26.11. Are plans provided adequate to assist emergency response and meet the requirements of Regulation 6 of the Fire Safety Regulations 2022?

HCC have produced plans to meet Regulation 6 of the Fire Safety Regulations 2022.

Confirmation of Regulation 11 of the Fire Safety Regulations 2022

26.12. Has the responsible person provided the local fire and rescue authority adequate documentation relating to Regulation 5 (design and materials in external walls)? This information must be communicated via electronic means.

It can be confirmed that HCC have previously provided HFRS with the necessary documentation which meets the requirements of Regulation 5 (design and materials in external walls) further to surveys carried out.

Although findings of the survey stated that external walls systems met the functional requirements of Building Regulations and did not contain ACM's, reports provided limited information and potentially fall short of today's benchmarks for a PAS 9980 external wall survey.

Refer to 16.1.



Photo 105

26.13. Has the responsible person provided the local fire and rescue authority adequate documentation relating to Regulation 6 (floor plans and building plan)? This information must be communicated via electronic means.

Yes.

27. Resident and stakeholder engagement - communication & information

Regulation 9 of the Fire Safety Regulations 2022, the responsible person must display fire safety instructions in a conspicuous part of any building:

- which contains two or more sets of domestic premises; and
- which contains common parts through which residents
- would need to evacuate in the case of an emergency.

Fire safety instructions must be in a comprehensible form that the residents can be reasonably expected to understand; they must also contain instructions relating to the evacuation strategy for the building, how to report a fire to the fire and rescue authority, and any other instruction that tells residents what they must do when a fire has occurred.

The responsible person must provide a copy of the instructions to a new resident of domestic premises within the building, as soon as reasonably practicable after that resident moves into the premises; and to all residents of domestic premises within the building within each period of 12 months beginning with the date these Regulations come into force.

After any material changes to the instructions, the responsible person must display the fire safety instructions and provide a copy to residents which relate to evacuation, how to report an incident and any other instruction of actions to be taken in the event of a incident.

27.1. Are arrangements in place to meet the requirements of Regulation 9?

HCC confirmed that significant efforts are being made to improve engagement and communication with residents; a clear and defined example of this is the creation of the Tenancy Management High Rise Team. In addition, HCC have created various steering and residents groups which undertake monthly surgeries who are to be attended by emergency services - police, fire, anti social groups etc.

HCC are currently in the process of producing a 'Welcome Pack / Resident Information Pack'; these safety packs are to cover the contents stated below along with resident duties, HCC obligations, key contacts within HCC and how to report defects / incidents etc.

HCC have committed to community drop-ins to assist engagement along with producing periodic briefing letters which provide updates - good and bad & feedback forms.

Another clear and defined demonstration of engagement is installing smart tv's on landings which are to be used for communicating with residents.

Consulting and notifying residents is critical to the safety of the building. The points below should be cross-referenced with information provided to residents to ensure adequate communication is in place. BS 9991:2015 Annex F Figure F.1 provides a suitable example of such advice, or residents may be provided with specific information in the form of a bespoke document. The term 'They' refers to Residents.

• How they can prevent fires in their own home and in the common parts.

Yes

• The importance of maintaining the security of their block (making sure doors close behind them when they enter or leave) and being vigilant for deliberate fire setting.

• that they should never store or use petrol, bottled gas, paraffin heaters or other flammable materials in their flats.

• what action they should take if they discover a fire.

• how they can ensure they can make their way safely from their flats and how to exit the building once they have left their flat.

• what 'stay put' means if there is a fire elsewhere in the building.

• what they must do to safeguard communal escape routes, especially taking care to make sure fire doors self-close properly and are not wedged, tied or otherwise held open.

• what the policy on the use of common parts requires of them.

• how they can avoid inadvertently damaging the buildings fire protection when making changes to their flat. what is involved in testing their smoke alarms and how often they should do it.

• ways they can assist the fire and rescue service by not blocking access when parking, and by keeping fire main inlets and outlets, where provided, clear.

• how they can report essential repairs needed to fire safety measures in their flat and elsewhere in the block.

27.2. Are arrangements in place to provide residents with sufficient information to meet guidance provided in BS 9991:2015 Annex F Figure F.1?

As described above.



Photo 106

Fire doors

Regulation 10 of the Fire Safety Regulations 2022, the responsible person, in relation to a building which contains two or more sets of domestic premises and which contains common parts through which residents would need to evacuate in the case of an emergency, must provide the required information about fire doors to the residents of the building.

Required information includes:

- Fire doors should be kept shut when not in use;
- Residents or their guests should not tamper with the self closing devices; and

• residents should report any faults or damages with doors immediately to the responsible person;

The required information must be provided by the responsible person to a new resident of domestic premises in the building, as soon as reasonably practicable after that resident moves into the premises; and to all residents of domestic premises within the building, within each period of 12 months beginning with the date these Regulations come into force.

The responsible person, in relation to a building which contains two or more sets of domestic premises and which is above 11 metres in height, must use best endeavours to undertake checks of fire doors at the entrances of individual domestic premises in the building at least every 12

months.

The responsible person in relation to a building which contains two or more sets of domestic premises and which is above 11 metres in height, must undertake checks of any fire doors in communal areas of the building at least every 3 months.

The responsible person must keep a record of the steps taken to comply with the obligation including in any case where access to the domestic premises was not granted during any 12 month period, and the steps taken by the responsible person to try and gain access. The checks required must include ensuring that the self-closing devices for the doors are working.

27.3. Are arrangements in place to meet the requirements of Regulation 10?

HCC have produced a Fire Safety in flats document which meets the requirements Regulation 10 of the Fire Safety Regulations 2022.

28. Management of fire safety

28.1. Fire safety at the premises is managed by:

Fire Safety in HCC's HRRB's is managed by Hull City Council with the Assistant Director seen as the most appropriate and senior role responsible for Fire Safety.

28.2. To meet Article 18 of the Fire Safety Order - Safety assistance and inline with recommendations made by WG8 and

Hackitt report (Building A Safer Future) Recommendation 3.1c), have those in control of the building nominated a 'Building Safety Manager' (BSM). This role should be nominated as the 'named individual' who is the single point of contact responsible for all safety issues in the premises. The BSM must have the 'relevant skills, knowledge, experience and behaviours, to carry out the day to day management of the fire and structural safety of the building, having regard to thestatutory functions of the BSM'.

Rebecca Franks is nominated as the Building Safety Manager (BSM).

28.3. Safety assistance continued: Are competent person(s) appointed under Article 18 of the Fire Safety Order to assist the responsible person in undertaking the preventive and protective measures (i.e. relevant general fire precautions)?

The structure of the organisation at HCC is complex and it is currently unclear from a third party's point of view who is responsible for each area associated with Fire Safety. As with any Local Authority, different departments are responsible for different areas of the organisation, it is the opinion of Holistic Fire Safety that HCC should document the organisational structure and roles responsible for fire safety.

See the attached as guidance:

There should be a formal agreement between duty holders and key roles such as Assistant Director, Head of Service, Families & Neighbourhoods etc. Their roles and responsibilities should be documented in the form of a matrix. The matrix should clearly identify the agreed responsibility for every key aspect of fire safety management specific to HCC.

(duty holders include anyone who, "under a tenancy or contract, has a responsibility for maintenance or repair of the premises, maintenance or repair of anything in or on the premises, or for the safety of the premises". This can include a wide variety of people, including, third party contractors on short and long term agreements, along with fire risk assessors and service engineers who maintain fire protection equipment; roles who may commit offences if they do not carry out their work properly.)



Photo 107

28.4. Do those in control of the building have a Fire Safety Management Plan in place which demonstrates how fire safety is managed across the organisation. The management plan should be a single and central document which provides evidence of compliance with Article 11 of the Fire Safety Order - Fire safety arrangements.

Verbal discussions with HCC representatives confirmed that HCC have a number of policies and procedures in place which confirmed compliance with Article 11 of the Fire Safety Order.

TCW is the electronic recording database which is defined as the buildings fire safety manual.

As described previously Holistic Fire Safety are to complete an audit/assessment of the management of HRRBs - this audit/assessment will confirm whether current provisions are satisfactory.

28.5. Does the premises have a fire safety design strategy document?

• A complete and thorough consideration of the fire safety requirements and its occupants

• To widen the consideration of fire precautions with respect to broader objectives including life safety, business continuity and property protection

- To assist in the review of fire system design criteria prior to the preparation of the designs
- To ensure that fire protection system designs support the strategy
- To provide a framework for all future fire safety and protection works

There is no fire strategy design document in place for Block 1.

28.6. Does the property have a database/fire safety manual which contains the following information?

- Building design information
- Building plans inc. locations of isolation points, fire hazards & hydrants
- Drawings of the building identifying the fire alarm zones and compartment boundaries
- Drawings defining levels of fire-resistance in accordance with the fire strategy
- Fire Risk Management Plan
- Fire risk assessment
- Routine test inspection and maintenance of passive and active systems
- Details of fire safety training
- Record and action plan of any fire safety audit and programme of works to remedy defects and deficiencies
- Evacuation procedures
- Business continuity plans
- Emergency Plan
- Safe working procedures

TCW is the electronic recording database which is defined as the buildings fire safety manual.

28.7. Are those who occupy the premises as a 'place of work' provided with fire safety training specific to the building? In relation to Article 11 of the Fire Safety, fire safety training should cover:

• The premises fire safety strategy and procedures and their personal responsibilities to prevent and protect against outbreaks of fire

• What action to take if they discover a fire

• How to raise the alarm, the location of manual call points, and the procedure for contacting the Fire Service

• What action to take immediately on hearing the fire alarm

• The location and safe use of portable or other fire extinguishing equipment (if authorised to do so)

• The location of escape routes from their place of work including those routes not used regularly for normal access and egress

• Their responsibility to direct or escort visitors and contractors in their charge to escape routes (and in the case of disabled persons to the nearest useable escape route)

• The importance of keeping closed all fire doors and windows to limit the spread of fire, heat or smoke

• How to safely isolate or shutdown process plant or equipment, where appropriate

• The importance of good housekeeping in preventing the outbreak of fire and limiting its effects.

It has been confirmed that HCC representatives are provided with fire safety training upon induction and at periodic intervals.

Regulation 7 of the Fire Safety Regulations 2022, relates to routine test, inspection and maintenance of lifts and essential firefighting equipment. It is important to demonstrate to the legislative enforcing authority and Building Safety Regulator that the building has a comprehensive testing and recording programme of passive and active protection relating to the overall functioning of the building; such demonstration of planned preventative maintenance provides for a good fire safety culture and reduce the possibility of ignition.

28.8. Are arrangements in place to inspect, test, and maintain lifts and essential fire fighting equipment within the premises?

TCW is the electronic recording database which is defined as the buildings fire safety manual and this is where all records associated with all HCC's HRRB's are stored.

Verbal discussions confirmed that compliance plans & maintenance programmes are in place which detail test, inspection and maintenance frequencies for lifts and all essential fire fighting equipment.

Management audits should view records and ensure compliance with the appropriate British Standards.

It can be confirmed that arrangements are in place to notify the local fire and rescue authority if there are any changes which affect their ability to gain access to the building, carry out search and rescue or carry out firefighting operations.

<u>https://humbersidefire.gov.uk/your-safety/business-safety/fser</u> Regulation 7 of the Fire Safety Regulations 2022, relates to routine test, inspection and maintenance of lifts and essential firefighting equipment. It is important to demonstrate to the legislative enforcing authority and Building Safety Regulator that the building has a comprehensive testing and recording programme of passive and active protection relating to the overall functioning of the building; such demonstration of planned preventative maintenance provides for a good fire safety culture and reduce the possibility of ignition.

Where the responsible person identifies any fault with a lift for use by firefighters, evacuation lift or piece of essential fire-fighting equipment, are arrangements in place for the responsible person to rectify the fault?


Where a fault identified cannot be rectified within a 24-hour period beginning with the time the fault is identified, the responsible person must, as soon as reasonably practicable report the fault to the local fire and rescue authority by electronic means; and subsequently report the rectification of the fault to the local fire and rescue authority by electronic means when it has been rectified

Media summary




Photo 1














































































































ADB B1 Diagram 3.3

Photo 51




























































d. that all high-rise residential buildings (both those already in existence and those built in the future) be equipped with facilities for use by the fire and rescue services enabling them to send an evacuation signal to the whole or a selected part of the building by means of sounders or similar devices;

Photo 79

Table 8	Provisions for emergency escape lighting				
	Occupancy characteristic	Areas needing emergency escape lighting			
	A	Underground or windowless accommodation			
		Stairways in a central core or serving storey(s) more than 18 m above ground level			
		Internal corridors more than 30 m long			
		Open-plan areas of more than 60 m ²			
	B A)	All escape routes ^{B)} (except in shops of three or fewer storeys with no sales floor more than 280 m ² provided that the shop is not a restaurant or bar)			
	¢	All common escape routes ^{®)} , except in two-storey blocks of flats			
	Any use	All sanitary accommodation with a floor area over 8 m ²			
		Windowless sanitary accommodation with a floor area not more than 8 m ²			
		Electricity and generator rooms			
		Switch room/battery room for emergency lighting system			
		Emergency control room			
	A) In areas of sho	ps where the public are not admitted use occupancy characteristic A.			
	a) Including exter	rnal escape routes.			







































Bransholme	Fire	Station	
Diananounic	1 11 0	oracion	

12 Noddle Hill Way, Hull HU7 4SH

Ť	Head south-west on Noddle Hill Way towards Upavon Garth
	210 (t
4	Turn left onto Wawne Rd
	0.2 ml
ţ	At the roundabout, take the 1st exit onto Robson Way/B1237
	1.8 mi
Ф	At the roundabout, take the 3rd exit onto Diadem Grove
	0.1 ml
Ģ	At the roundabout, take the 2nd exit onto Greenwich Ave
	0.2 m)
1	Turn right onto Barham Rd
	213 ft
4	Turn left onto Valiant Dr
	223 ft.
Valia	ant Dr
Hull	

Photo 99









Reporting a Fault	
Regulation 7 of the Fire Safety (England) Regulations 2022 requires the Responsible Person all high-rise related all huldings to understate monthly checks of key findinghing explorent within the building. Where finals are lateritised which cannot be exciled within 24 hours, then the Responsible Reson must report the fault to the local fine and rescue service as some are the Responsible Resonance and the rescue service needs to be referred within the fault has been received.	
* Required	
Premises details	
1. Name of Building *	
Enter your answer	
2. Address of building *	
Enter your answer	
3. Postcode of building * Enter your answer	
4. UPRN of building (of known) The UPRN is a unique identifier for addressing purposes, it enables fire and rescue service to connect data internally and externally with other organisations using the OS AddressBase products. The UPRN for any property in England can be easily found using the following website: <u>https://www.fordmeddersco.co.k/</u>	
The value must be a number	
5. Name of Responsible Person * The Responsible Person will be the organisation who has control of the premises in connection with carrying on a business. This will usually be the freeholder, the managing gravits for the buding, or a reademict management company.	
Enter your answer	
6. Telephone number for Responsible Person	
Enter your answer	
7. Email address for Responsible Person	
Enter your answer	





Aspect of Fire Safety Management	Agreed Responsibilities					
	Operations	Misusting Projekter	Managing Agent or Pacifices Managers M officent born tousing provider)	Care Provider	Commissione of Berdices	
Lead duty triader?			1			
Building fire risk eklekainent						
Person-control fre mit assessment (where appropriate)					-	
Festing of fire alarmi system						
Maintenance of the alarm system						
Testing of emergency lighting						
Maintenance of emorganity lighting.					-	
Tinking of sprinklet system		-		-		
Marrisonance of acreshine systems			-			
Feating of amone vertil			-	-		
Maintenance of success wetts						
Testing of dox release relations	-		-	-	-	
Mathematica of door release mechanisms						
Testing of social alarm system		-		-	-	
	-			-	-	
Aspect of Fire Ballety Management	Agreed Responsibilities					
	Ownerlanding	the state	Managing Agard or Fapilities Managers (F althurset from Insceling provider)	Care Presiden	of Services	
Menderstrop of rootsk were system						
Reading Incompany Republication Parameters threaking for dense. For each dense and constitue- of the autoparameters, etc.					1	
Manufacture of fina classes						
Maintanance of the anticipationers						
Mandanana of dang hama		-				
Materians of hybrid protection system						
President of the soluty relationships to result					1	
Organg engegment and methods regering. Ne promiser					1	
Origining imagingement with measures in remind them of the proceedings					1.000	
Europ chemise (if angestimustation)						
Maintaining a record of the fine safety incordination	1				1.00	
Ensuring that firs proceedures are up to dela						
Liamony with hand first mult reacture servicel prevent						
Treating of ident	1		1.1			
Aspect of Fire Safety Management	Agreed Responsibilities					
	Desertantion	Housing	Managing Agent	Case Provider	Commissione	
		Previller	or Pacifica Managers (M different burn housing provider)		of Berulius	
Inspections during contractors' works						
Provision of information to putade contractors						
Recording false alartim						
Holding of relevant records re being maintenence, training, drills, etc.			1.1.1.1.1		1	

Source: Fire Safety in Specialised Housing

File summary

22291-VLTD1-01Aprov1-22291-VLTD1-00.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-01.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-00.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-01.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-02.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-03.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-04.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-05.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-06.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-07.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-08.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-09.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-10.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-11.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-OP.pdf 22291-VLTD1-01Aprov1-22291-VLTD1-VS.pdf